

# Marine Safety Flash

## A15-15 (15<sup>th</sup> July)



### Finger Pinch Injury

#### Incident Overview

IP was undertaking vessel transfer from Crew Transfer Vessel to Accommodation Vessel Fast Recovery Craft (FRC). As the IP disembarked from the CTV, holding onto the transom hatch cover, the unsecured cover fell onto the IP's finger, on their right hand, causing injury. The IP was wearing appropriate gloves at the time of the injury.

#### Key Findings


- IP reported to Supervisor
- IP taken to Doctor on Accommodation Vessel
- IP taken off island for further assessment

#### Recommendations

- Is risk assessment appropriate/ adequate and are being followed?
- Ensure that hardware is fit for purpose e.g. latching mechanism



Pinch Point



Cover in closed position



Re-enactment